



Property Condition Report

**12 Cross Street
Regent
Whangarei District**

Client: Paul Sumich

Inspection Date: 31/07/2020

REPORT CONTENTS

REPORT INTRODUCTION	3
EXECUTIVE SUMMARY	4
PROPERTY DESCRIPTION	6
CLIENT & INSPECTION DETAILS	7
SITE FEATURES	8
NORTH ELEVATION	9
EAST ELEVATION	11
SOUTH ELEVATION	13
WEST ELEVATION	15
FOUNDATION	17
ROOF	20
ROOF SPACE	22
KITCHEN	24
LOUNGE	26
BEDROOM 1	27
BEDROOM 2	28
BEDROOM 3	29
BEDROOM 4	30
BATHROOM 1	31
ENSUITE	33
DETACHED GARAGE	35
DWELLING SERVICES	37
INSPECTION SCOPE & STATEMENT OF POLICY	39

REPORT INTRODUCTION

Dear Paul Sumich.

RE: Property Inspection Report: 12 cross Street, Regent.

Thank you for the opportunity to provide you with the following report, we hope it aids you with your investment.

This report has been compiled following a site inspection carried out on the 31/07/2020.

Please read this report in its entirety.

This report should not be seen as an all-encompassing report dealing with a building from every aspect, but rather a reasonable attempt to identify any significant defects visible at the time of the inspection.

This report is not a warranty against problems developing with the building after the date of the report. It is outside the scope of this report to investigate, or comment on if the dwelling complies with any building code legislations or local body bylaws.

Scope Building Surveyors recommend that quotes and advice are sought from Independent Qualified Persons on receipt of the property report for a more specific qualification of comments made by Scope Building Surveyors in the report, regarding any faults or defects identified, if more intrusive investigation is desired or simply in relation to any comment made.

This also applies to any verbal communication made by Scope Building Surveyors regarding any faults or defects identified or comments made.

If you require any clarification or wish to discuss any details of the report, please do not hesitate to contact us.

Yours sincerely

Scope Building Surveyors Ltd

EXECUTIVE SUMMARY

Overall based on a visual examination, the property exterior as inspected is considered to be in an average condition for the age of the property and the materials and finishes incorporated.

The interior of the House is again in an average condition considering the age of the fittings and finishes.

The following items have been flagged during the inspection and need to be taken in to consideration.

REPAIR OR REPLACEMENT RECOMMENDED

EAST ELEVATION

CLADDING SYSTEM

Findings:

Visible cladding void to exterior kitchen wall. We recommend sealing this junction to reduce the risk of moisture ingress. There were no elevated moisture readings in this area at the time of inspection.

WEST ELEVATION

CLADDING SYSTEM

Findings:

Poor seal to heat pump penetration. We recommend sealing this junction to ensure penetration remains weathertight.

ROOF

GUTTERS

Findings:

Gutter system separated on slip joint, will require repair. No down pipes installed to veranda. These should be installed to ensure rain water is diverted away from the building.

DOWNPIPES

Findings:

No spreader pipe installed. We recommend the installation of a spreader pipe to ensure rain water is diverted evenly on to roof covering.

KITCHEN

BENCH TOP

Findings:

Poor seal between bench top and window joinery. We recommend the installation of a suitable splash back/sealed detail to ensure this junction remains watertight.

MAINTENANCE RECOMMENDED

ROOF

ROOF COVERING

Findings:

Visible corrosion around lead head fixings. Lead heads should be removed and replaced with new fixings. Roof covering should be inspected for signs of corrosion and treated with a suitable rust inhibitor where required.

GUTTERS

Findings:

Gutter system separated on slip joint, will require repair. No down pipes installed to veranda. These should be installed to ensure rain water is diverted away from the building.

SUMMARY CONCLUSION

Items noted in the following report should receive eventual attention, as some of these if left unattended may have the potential to affect the habitability of the house.

Further investigation is recommended for any item that may impede habitability; unsafe or hazardous; does not operate properly or perform its intended function in response to normal use.

Items identified as requiring repair or replacement either are or have potential to significantly affect habitability and/or can be considered as requiring reasonable expense to mitigate and should be evaluated by professionals in appropriate trades prior to closing.

Minor defects are common to most properties and may include minor blemishes, corrosion, cracking, weathering, general deterioration, unevenness, and physical damage to materials and finishes that could be expected with age, and general wear and tear.

PROPERTY DESCRIPTION

This four bedroom, two bathroom dwelling is situated on a flat section, above road level.

The building faces the road side to the South with access via a near level asphalt driveway providing access to a detached garage.

The dwelling has been constructed on a Type A - Timber floor with pile foundation.

Exterior cladding consists of painted timber weatherboard with a pitched timber framed roof clad in painted rolled metal with single glazed painted timber joinery.

The building appears to be originally constructed in the early 1900s with signs of structural alteration over the intervening years.

CLIENT & INSPECTION DETAILS

JOB BOOKING

Reference Number	2020/1272.
Property Address	12 Cross Street.
Inspection Type	Property Condition Report.
Date of Inspection	31/08/2020.
Time of Inspection	11:00 AM.
Property Type	Residential.
Present at Inspection	Vendors Agent.
Occupancy	Vacant.

CLIENT DETAILS

Report Commissioned by	Paul Sumich.
Phone Number	021 606460.

WEATHER CONDITIONS

Atmosphere	Overcast.
Soil	Soil conditions were damp at the time of Inspection.

BUILDING CHARACTERISTICS

Approx Year of Construction	1900.
Building Type	Stand alone.
Levels	Single storey.
Building Orientation	South facing street.
Site Contour	Flat section, above road level.

UTILITY'S

Water Source	Mains Supply.
Sewage Disposal	Council Sewage System.
Power Supply	Overhead Power Supply.
Gas Supply	Gas is Supplied Via Cylinder.

SITE FEATURES

DRIVEWAY

Description Asphalt Surface.

SURFACE WATER CONTROL

Description Free Draining site.

NORTH ELEVATION

OVERVIEW

North Section:



CLADDING SYSTEM

Description:

Painted timber weatherboard, direct fixed.



EXTERIOR JOINERY

Description:

Timber joinery, painted and single glazed.



TIMBER DECKS & BALCONIES

Description:

Raised timber frame deck.



EAST ELEVATION

OVERVIEW

North Section:



CLADDING SYSTEM

Description:

Painted timber weatherboard, direct fixed.



Findings:

Visible cladding void to exterior kitchen wall. We recommend sealing this junction to reduce the risk of moisture ingress. There were no elevated moisture readings in this area at the tie of inspection.



EXTERIOR JOINERY

Description:

Timber joinery, painted and single glazed.



SOUTH ELEVATION

OVERVIEW

North Section:



CLADDING SYSTEM

Description:

Painted timber weatherboard, direct fixed.



EXTERIOR JOINERY

Description:

Timber joinery, painted and single glazed.



TIMBER DECKS & BALCONIES

Description:

Painted timber porch.



PATIO'S & PAVING

Description:

Concrete path providing access to front door.



WEST ELEVATION

OVERVIEW

North Section:



CLADDING SYSTEM

Description:

Painted timber weatherboard, direct fixed.



Findings:

Poor seal to heat pump penetration. We recommend sealing this junction to ensure penetration remains weathertight.



EXTERIOR JOINERY

Description:

Timber joinery, painted and single glazed.



FOUNDATION

CONSTRUCTION TYPE

Description:

Type A - Timber floor with piles.

SUBFLOOR ACCESS

Description:

Subfloor access located on the West elevation. Subfloor inspected from manhole.



FOUNDATION WALL

Description:

Slatted timber base boards.

GROUND CONDITION

Description:

At the time of inspection subfloor ground conditions were dry.

PILES

Description:

Timber piles.



Findings:

Timber pile visible from access appears to be damaged. We recommend engaging the services of a LBP to replace this pile as required.



SUBFLOOR FRAMING

Description:

150x50mm timber floor joists.



FLOORING

Description:

Unable to visibly identify due to the installation of subfloor insulation.

SUBFLOOR SERVICES

Description:

PVC waste connections.
Polybutene plumbing.



SUBFLOOR VENTILATION

Description: Ventilation via slatted perimeter base boards.

VAPOUR BARRIER

Description: No vapour barrier present.

INSULATION

Description: Segmented polystyrene.



Approximate Thickness: 100mm.

ROOF

ROOF COVERING

Accessibility:

Roof covering inspected from the access of a 3.6m ladder only. Inspection of areas not visible from the access of a 3.6m ladder may require additional access such as scaffolding or a fall arrest system.

Description:

Painted profiled metal.



Findings:

Visible corrosion around lead head fixings. Lead heads should be removed and replaced with new fixings. Roof covering should be inspected for signs of corrosion and treated with a suitable rust inhibitor where required.



GUTTERS

Description:

PVC gutter system.

Findings:

Gutter system separated on slip joint, will require repair. No down pipes installed to veranda. These should be installed to ensure rain water is diverted away from the building.



FASCIA

Description: Painted timber fascia boards.

DOWNPIPES

Findings:

No spreader pipe installed. We recommend the installation of a spreader pipe to ensure rain water is diverted evenly on to roof covering.



ROOF SPACE

ACCESS

Location

Access to roof space restricted at the time of inspection. Unable to safely access roof space.



ROOF CONSTRUCTION

Description:

90x50mm timber rafters.



ROOF COVERING UNDERLAY

Description:

No underlay.



INSULATION

Description:

Bulk insulation segments between ceiling joists.

Approximate Thickness:

180mm.

ELECTRICAL WIRING

Description:

Visible roof space Electrical wiring consists of TPS.

KITCHEN

LOCATION

Description: Open plan with Lounge.



FLOOR COVERING

Description: Polished T&G.

WALL LINING

Description: Painted Plasterboard.

CEILING

Description: Painted Plasterboard.

KITCHEN JOINERY

Description: Meltica Carcass.

BENCH TOP

Description: Stone.

Findings:

Poor seal between bench top and window joinery. We recommend the installation of a suitable splash back/sealed detail to ensure this junction remains watertight.

SINK

Description: Ceramic basin.

OVEN

Description: Gas oven 6 burner.

RANGE HOOD

Description: Wall hung unit vented through exterior wall cladding.

ELECTRICAL PROVISIONS

Description:

Sockets tested and working at the time of inspection.

LOUNGE

LOCATION

Description: Open plan with Kitchen.

FLOOR COVERING

Description: Polished T&G.

WALL LINING

Description: Painted Plasterboard.

CEILING

Description: Painted Plasterboard.

ELECTRICAL PROVISIONS


Description: All sockets tested and working at the time of inspection.

BEDROOM 1

LOCATION

Description:

Off hallway.



FLOOR COVERING

Description:

Carpet floor covering.

WALL LINING

Description:

Painted Plasterboard.

CEILING

Description:

Painted Plasterboard.

INTERIOR JOINERY

Description:

Painted solid timber door.

ELECTRICAL PROVISIONS

Description:

All sockets tested and working at the time of inspection.

BEDROOM 2

LOCATION

Description:

Off hallway.



FLOOR COVERING

Description:

Carpet floor covering.

WALL LINING

Description:

Painted Plasterboard.

CEILING

Description:

Painted Plasterboard.

INTERIOR JOINERY

Description:

Painted solid timber door.

ELECTRICAL PROVISIONS

Description:

All sockets tested and working at the time of inspection.

BEDROOM 3

LOCATION

Description: Off hallway.



FLOOR COVERING

Description: Carpet floor covering.

WALL LINING

Description: Painted Plasterboard.

CEILING

Description: Painted Plasterboard.

INTERIOR JOINERY

Description: Painted solid timber door.

ELECTRICAL PROVISIONS

Description: All sockets tested and working at the time of inspection.

BEDROOM 4

LOCATION

Description: Off hallway.

FLOOR COVERING

Description: Carpet floor covering.

WALL LINING

Description: Painted Plasterboard.

CEILING

Description: Painted Plasterboard.

INTERIOR JOINERY

Description: Varnished solid timber door.

ELECTRICAL PROVISIONS

Description: All sockets tested and working at the time of inspection.

BATHROOM 1

LOCATION

Description: Off hallway.



FLOOR COVERING

Description: Polished T&G.

WALL LINING

Description: Painted Plasterboard. Tiled wall linings.

CEILING

Description: Painted Plasterboard.

INTERIOR JOINERY

Description: Painted solid timber door.

VANITY

Description: Freestanding melteca carcass with composite top.

SHOWER

Description: Modular shower unit with tiled wall linings, glass door and composite base.
Water Pressure: Average water pressure at the time of inspection.

BATH

Description: Freestanding bath.

TOILET

Description: S-Trap, Ceramic bowl, dual flush ceramic cistern.

VENTILATION

Description: Passive ventilation via window.

ELECTRICAL PROVISIONS

Description:

All sockets tested and working at the time of inspection.

ENSUITE

LOCATION

Description:

Master bedroom.



FLOOR COVERING

Description: Polished T&G.

WALL LINING

Description: Painted Plasterboard. Tiled wall linings.

CEILING

Description: Painted Plasterboard.

INTERIOR JOINERY

Description: Painted solid timber door.

SHOWER

Description: Modular shower unit with tiled wall lining, glass door and composite base.

TOILET

Description: S-Trap, Ceramic bowl, dual flush ceramic cistern.

VENTILATION

Description: Mechanical ventilation via extraction unit.

ELECTRICAL PROVISIONS

Description: All sockets tested and working at the time of inspection.

DETACHED GARAGE

OVERVIEW

Section:



CLADDING SYSTEM

Description:

Painted timber weatherboard.

EXTERNAL JOINERY

Description:

Painted single glazed timber joinery.

ROOF COVERING

Accessibility:

Inspection carried out from 3.6m ladder.

Description:

Painted profiled metal.



GUTTERS

Description:

PVC gutter system.

FASCIA

Description: Painted timber fascia boards.

DOWNPIPES

Description: PVC downpipes discharging to Council Stormwater.

FLOOR COVERING

Description: Bare Concrete floor.

GARAGE DOOR

Description: Double sectional door, automatic opener.



ELECTRICAL PROVISIONS

Description: All sockets tested and working at the time of inspection.

DWELLING SERVICES

HEATING SYSTEMS

Description:

Heat pump. This unit was not assessed as it falls outside the scope of this inspection, further inspection from a heating specialist is recommended.



Open fire place. This unit was not assessed as it falls outside the scope of this inspection, further inspection from a heating specialist is recommended.



ELECTRICITY SERVICES

Description:

RCD switchboard.



GAS SERVICES

Description:

Gas supplied from removable tank.



WATER SERVICES

Description:

Water supply to site via council mains.

Main connection valve location:

Toby located on at the road facing boundary.

HOT WATER SERVICES

Description:

Gas Calfont. This unit was not assessed as it falls outside the scope of this inspection, further inspection from a heating specialist is recommended.



FOUL WATER DISPOSAL

Description:

Foul water discharged to council supply.

INSPECTION SCOPE

This inspection is based on experience and reasonable opinion and is not a guarantee against moisture ingress at the time of inspection or in the future. This inspection has been carried out to the writer's best ability with all reasonable care taken using visual and non-invasive testing with meters as noted. This report is a guide only (as per NZS 4306:2005) and not a guarantee against moisture ingress or structural failure and is to be accepted as such by the owner.

All reasonable attempts have been made to identify any significant defects visible at the time of the inspection. The inspector has not moved furniture, fixtures, stored items, soils, plants, checked window/door locks, etc. at the time of inspection. He cannot see inside walls or other concealed areas and cannot detect damage or defects that are not visible in most cases. The aid of testing equipment was used at the time of inspection, but these tools have limitations and cannot detect defects in all circumstances.

Whether or not services have been used for some time prior to an inspection being carried out may affect the detection of leaks and other defects. For example, in the case of a shower enclosure, the absence of any dampness at the time of inspection does not necessarily mean that the enclosure will not leak.

A Trotec T660 non-invasive moisture meter was used as an aid in this inspection. This in itself cannot be used to confirm or eliminate the possibility of moisture or deterioration in the framing timber or underlying materials. It is of limited use with some plaster systems and other factors.

This property report is not a Code of Compliance Certificate or a Certificate of Acceptance under the Building Act. It is also not a statement that the property complies with the requirements of any other Act, regulation or by-law. Nor is this property report a warranty against problems developing with the building after the date of this report. This inspection should not be confused with an appraisal, building code inspection or any guarantee of any kind, but as a tool to aid you to be better prepared and knowledgeable.

Inspections – over three meters. Worksafe regulations state that working at heights over three meters is done safely. If climbing over three meters then Worksafe state – guarding, safety nets or fall arrest systems should be in place. This is impracticable in the situation of house inspections, therefore our policy is, that Inspector's only climb as far as their ladders take them, keeping their own personal safety paramount.

Reasonable access – areas where safe, unobstructed access is provided and the minimum clearance's specified below are available; or where these clearance's are not available, areas within the inspector's unobstructed line of sight:

Roof space – access manhole 450 x 400mm; crawl space 600x 600mm; height accessible from a 3.6m ladder or such other means of access that meet H&S requirements.

Subfloor – access manhole 500 x 400mm; crawl space vertical clearance timber floor 400mm (from underside of bearer) Concrete floor 500mm.

Roof exterior – accessible from a 3.6m ladder or such other means of access that meet Worksafe requirements.

This inspection has been undertaken in accordance with the guidelines as set down by Standards New Zealand NZS4306:2005.

STATEMENT OF POLICY

- a) This is a report of a visual only, non-invasive inspection of the areas of the building which were readily visible at the time of inspection. The inspection did not include any areas or components which were concealed or closed in behind finished surfaces (such as plumbing, drainage, heating, framing, ventilation, insulation or wiring) or which required the moving of anything which impeded access or limited visibility (such as floor coverings, furniture, appliances, personal (property, vehicles, vegetation, debris or soil).
- b) The inspection did not assess compliance with the NZ Building Code including the Code's weather tightness requirements, or structural aspects. On request, specialist inspections can be arranged of weather tightness or structure or of any systems including electrical, plumbing, gas or heating.
- c) The purpose of the inspection was to assess the general condition of the building based on the limited visual inspection described in this report and may not identify all past, present or future defects. Descriptions in this report of systems or appliances relate to existence only and not adequacy or life expectancy. Any area or component of the building or any item or system not specifically identified in this report as having been inspected was excluded from the scope of the inspection.
- d) This report has been prepared on the basis of a visual inspection of the building works using normal readily available access, and without testing of components for the assessment of the overall structural condition of it and associated items, and without recourse to construction drawings.
- e) This report is based on experience and reasonable opinion however is not a guarantee against moisture ingress at the time of inspection or in the future. This inspection has been carried out to the writer's best ability with all reasonable care taken using visual and non-invasive testing with meters as noted. This report is a guide only (as per NZ Standard 4306:2005) and not a guarantee against moisture ingress or structural failure and is to be accepted as such by the owner.
- f) It is confirmed that no detailed geotechnical investigation has been included in this brief. An investigation of the condition and location of underground drainage and services and of electrical, gas and plumbing (except as otherwise may be described in this report) is not included in this brief.
- g) No warranty can be given as to other defects, not apparent to visual inspection at the time; inclusive of underground services, waterproofing, soil stability or the moisture content in partitions or exterior cladding's.
- h) Weather conditions can affect moisture found e.g. long dry spells, driving rain in certain directions which can cause localised leaks and may only occur three to four times per year. Guidelines as below, flashings, ground levels, etc. This stresses the importance of flashings, ground levels, etc., which may be highlighted in this report.
- i) This property report does not include the structural, electrical, plumbing or gas piping and fitting, home heating state of the premises, as our consultants are not qualified for this but can arrange for these areas to be inspected by those people whose qualifications enable them to do so.
- j) This report does not include any positioning of building or improvements in relation to site boundaries, or provide any guarantee whatsoever those items surveyed will not fail at some later date, and information herein pertains strictly to observations the day of inspection and accessibility only.
- k) If the property is controlled by a Body Corporate or similar it would be recommended prior to purchase a copy of the minutes be obtained from the Corporate Secretary to establish the history of the inspected property or other properties under such Body Corporate. This inspection has been undertaken on this sole dwelling and does not extend to remainder of complex, or common areas. The inspection is confined to the above property only and does not cover structural integrity of the entire complex.
- l) This document and information contained within is intended only for the use of the addressee named above.

All reasonable measures have been employed to detect possible defects but give no warranty against, and is not limited to:

- m) the assessment of an apparent defect which may be subject to extreme weather conditions
- n) misinformation supplied by vendor, agent, person for whom report being prepared.
- o) concealment, intentional or otherwise, of a possible defect.
- p) assessment of any apparent defect which may occur intermittently or usually occurs after regular use.

- q) presence of chattels, furnishings and personal effects
- r) adequacy of footings
- s) adequacy of concealed damp-proof membrane's
- t) adequacy of concealed drainage
- u) swimming pools, spa pools, sauna's and associated equipment
- v) the operation of fireplaces and chimneys
- w) intercom systems
- x) floor coverings
- y) appliances, including but not limited to; dishwasher's, waste disposal units, ovens, ducted vacuum systems
- z) structural stability (other than pipe instability)
- aa) hazards including but not limited to Asbestos and Illicit Substance contamination.
- ab) hot water cylinders
- ac) window/door locks, bolts, etc.
- ad) any other factors limiting the preparation of this report.

CONFIDENTIAL REPORT: The inspection report is **prepared for the client solely and exclusively** for the clients own information and may not be relied upon by any other person. The client agrees to maintain the confidentiality of the inspection report and agrees not to disclose any part of it to any other person. The client may distribute copies of the inspection report to the seller and the real estate agents directly involved in this transaction, but said persons are not specifically intended beneficiaries of this agreement or the inspection report. The client and the inspector do not in any way intend to benefit said seller or the real estate agents directly or indirectly through this agreement or the inspection report. The client agrees to indemnify, defend and hold the inspector harmless from any third party claims arising out of the clients unauthorised distribution of the inspection report.